


TH-67 OPERATOR'S SUPPLEMENT

HEADQUARTERS
110TH AVIATION BRIGADE
FT. RUCKER, AL 36362
26 SEPTEMBER 2008

CHANGE
NO. 2

- a. Collective-Increase if near the ground to prevent main or tail rotor ground contact.
 - b. Pedal- Apply in the direction of turn.
 - c. Direct assistance with flight control inputs to level the aircraft.
 - d. Land as soon as possible.
2. Retain this sheet in front of supplement for reference purposes.

By order of:


TERRENCE J. DOLAN
Colonel, Aviation
Commanding